

Asbestos Analysis Report - XRD

This Report replaces Report 20-4603-01A-AN



Report No.: 20-4603-01B-AN
Date of Report: 29/8/2016
Date of Sampling: As Received
Client: Fireproof Cladding Facades Pty Ltd
Client Address: 2/1 Laser Drive, Rowville VIC 3178
Client Contact: Gary Costa
Site Address: Asbestos Analysis - As Received

Introduction:

Clearsafe Environmental Solutions Pty Ltd (Clearsafe) was requested by Gary Costa of Fireproof Cladding Facades Pty Ltd to analyse a bulk sample of fibrous board by X-Ray Diffraction method to assess the presence of Asbestos. The sample has been identified by the client as UltraMgO, Magnesium Oxide Board and labelled as Sample Number 20-1040/431.

Analysis by XRD has reported that Asbestos-sized fibres were not detected. Asbestos-forming minerals were not detected. Refer to Laboratory Report, 98358.

Notes and Limitations:

All work is conducted in a conscientious and professional manner, with due diligence and appropriate care. However due to the disproportionate cost of potential damages or liability relative to the cost of our services, Clearsafe cannot offer any guarantee that all hazards have been identified. Subsequently, Clearsafe's liability to the client or any other party resulting from the performance or non-performance of the service, whether under contract law, tort law or otherwise, is limited to a maximum of up to five (5) times the total fee excluding expenses.

Clearsafe reports are not to be reproduced or reviewed except in full. All reports are prepared for a particular client's objective, and therefore should not be used by any third party as a basis for future decision-making.

Any Party that uses or relies on this document, in doing so acknowledges, on behalf of themselves and all other legal entities that they represent, the unequivocal approval, acceptance and endorsement of the limitations and exclusions stated within this document, else this document should not be used or relied upon for any purpose.

A handwritten signature in blue ink that reads 'M Fernandez'.

Prepared By: Michael Fernandez
Projects Manager

Clearsafe Environmental Solutions Pty Ltd ABN: 31 146 947 766
NATA Accredited Laboratory Number 18542
16 Stewart St, Wollongong NSW 2500
W: www.clearsafe.com.au E: info@clearsafe.com.au T: 1300 042 962



ISO9001:2008 Certified